


Rte. K east of Rte. 61/67

Bridge Replacement Project



Years of moisture have caused extensive deterioration to the underside of the bridge. The deterioration is so bad that one lane will be closed on the bridge.



The concrete on the bridge columns and under the bridge itself is cracking. The structural steel beams under the bridge are completely corroded.

